

ST_CASE	PER_NO	Activity	OSHA_No	WZ_Type	WZ_Incursion	Narrative	News_Link	Location_Summary	Month	Day	Sex	Age	State	Hour	Minute	Road (TWAY_ID)	Work Zone Type (WRK_ZONE)	Work Injury (WORK_INJ)	Crash Factors (CF1)	Person Factors (P_SF1)	Number of Parked/Working Vehicles Involved (PVH_INVL)	Alcohol Test Result (ALC_RES)	Relation to Road (REL_ROAD)	Location of Non-Motorist at Time of Crash (LOCATION)	Type of Intersection (TYP_INT)	Functional System (FUNC_SYS)
10010		LEGALLY INTOXICATED						INTERSTATE	1	28	Male	46	Alabama	22	15	I-65	Construction	No	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
10280		AT/NEAR VEHICLE BREAKDOWN				Female pedestrian killed in hit-and-run on Interstate 59 in Birmingham, car visible by center median barrier	<a href="https://www.al.com/news/birmingham/2018/05/pedestrian_struck_in_hit-and-r.html">https://www.al.com/news/birmingham/2018/05/pedestrian_struck_in_hit-and-r.html</a>	INTERSTATE	5	12	Female	18	Alabama	22	15	I-59	Construction	No	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
10376		LEGALLY INTOXICATED						Other Arterial/Collector/Local Road	4	20	Male	47	Alabama	23	19	W MOULTON ST SW	Construction	No	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
10668		WORKING		LANDSCAPING	MOTORIST INCURSION	Center Point city worker struck, killed while planting flowers in median	<a href="https://www.wbrc.com/2018/10/18/jeffco-authorities-investigating-fatal-traffic-accident-center-point-parkway/">https://www.wbrc.com/2018/10/18/jeffco-authorities-investigating-fatal-traffic-accident-center-point-parkway/</a>	AT/NEAR INTERSECTION	10	18	Female	62	Alabama	11	14	SR-N CENTERPOINT PKWY	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	2	NA	On Median	Median/Crossing Island	Four-Way Intersection	Principal Arterial - Other
40039		UNKNOWN						INTERSTATE	1	23	Male	19	Arizona	19	8	I-10	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
40095		CROSSING INTERSECTION						AT/NEAR INTERSECTION	1	26	Female	65	Arizona	0	27	BROADWAY RD	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Intersection-Unknown Location	Four-Way Intersection	Principal Arterial - Other
50159		JAYWALKING				5-year-old ran from home nearby onto highway under construction	<a href="https://www.fox16.com/news/local-news/neighbors-describe-horrific-and-heartbreaking-scene-following-accident/">https://www.fox16.com/news/local-news/neighbors-describe-horrific-and-heartbreaking-scene-following-accident/</a>	Other Arterial/Collector/Local Road	5	4	Female	5	Arkansas	18	37	US-64-090	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
50237		UNKNOWN						INTERSTATE	7	20	Male	41	Arkansas	1	16	I-530-050	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
61309		LEGALLY INTOXICATED						INTERSTATE	8	9	Male	30	California	1	45	I-15	Construction	Unknown	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
61452		JAYWALKING				Hit-and-run crash on off-ramp, woman believe to be a transient	<a href="https://timesofsandiego.com/crime/2018/08/14/hit-run-crash-kills-pedestrian-on-encinitas-freeway-off-ramp/">https://timesofsandiego.com/crime/2018/08/14/hit-run-crash-kills-pedestrian-on-encinitas-freeway-off-ramp/</a>	INTERSTATE	8	14	Female	62	California	99	99	I-5	Construction	Unknown	None	None/Not Applicable-Driver	0	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
61701		AT/NEAR RECENT CRASH						Other Arterial/Collector/Local Road	9	4	Male	54	California	23	36	SR-132	Construction	No	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable-Driver	0	Under Limit	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Principal Arterial - Other

62279	1	WORKING	1362420	UTILITY	MOTORIST INCURSION	Utility worker - N. Indian Road, Canyon & W. Tramview Dr - At 1:39 p.m. on November 27, 2018, an employee was prepping equipment as he was standing behind his line truck off the roadway. The employee was struck by a motor vehicle that collided with the back of the line truck, resulting in fatal crushing injuries.	<a href="https://www.osha.gov/pls/imis/inspection_detail?il?id=1362420.015">https://www.osha.gov/pls/imis/inspection_detail?il?id=1362420.015</a>	Other Arterial/Collector/Local Road	11	27	Male	45	California	13	44	INDIAN CANYON DR N	Construction	Unknown	None	None/Not Applicable-Driver	1	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Minor Arterial
62568	1	AT/NEAR VEHICLE BREAKDOWN				Exited Disabled vehicle & struck	<a href="https://www.ocregister.com/2018/06/15/2-dead-at-the-scene-3-injured-in-405-freeway-crash-in-seal-beach/#:~:text=SEAL%20BEACH%20%E2%80%944%20A%2039%20Year,405%20freeway%20in%20Seal%20Beach.&amp;text=The%20man%20and%20child%20got,also%20struck%20the%20disa">https://www.ocregister.com/2018/06/15/2-dead-at-the-scene-3-injured-in-405-freeway-crash-in-seal-beach/#:~:text=SEAL%20BEACH%20%E2%80%944%20A%2039%20Year,405%20freeway%20in%20Seal%20Beach.&amp;text=The%20man%20and%20child%20got,also%20struck%20the%20disa</a>	INTERSTATE	6	15	Male	39	California	2	35	I-405	Construction	Unknown	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
62568	2	AT/NEAR VEHICLE BREAKDOWN				Exited Disabled vehicle & struck	<a href="https://www.ocregister.com/2018/06/15/2-dead-at-the-scene-3-injured-in-405-freeway-crash-in-seal-beach/#:~:text=SEAL%20BEACH%20%E2%80%944%20A%2039%20Year,405%20freeway%20in%20Seal%20Beach.&amp;text=The%20man%20and%20child%20got,also%20struck%20the%20disa">https://www.ocregister.com/2018/06/15/2-dead-at-the-scene-3-injured-in-405-freeway-crash-in-seal-beach/#:~:text=SEAL%20BEACH%20%E2%80%944%20A%2039%20Year,405%20freeway%20in%20Seal%20Beach.&amp;text=The%20man%20and%20child%20got,also%20struck%20the%20disa</a>	INTERSTATE	6	15	Male	3	California	2	35	I-405	Construction	Unknown	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
62615	1	WORKING		UTILITY	MOTORIST INCURSION	She (SF City worker) and the rest of her crew were repairing a leak on 28th St in Noe Valley when she was struck and killed by a car that rolled off the bed of a tow truck	<a href="https://abc7news.com/sf-city-worker-killed-in-accident-was-single-mother-with-great-heart/3599514/">https://abc7news.com/sf-city-worker-killed-in-accident-was-single-mother-with-great-heart/3599514/</a>	Other Arterial/Collector/Local Road	6	13	Female	34	California	14	9	28TH ST	Construction	Yes	Motor Vehicle (In Transport 1983-2004) Struck By Falling Cargo or Something That Came Loose From or Something That Was Set in Motion By a Vehicle (Since 1983)	None/Not Applicable-Driver	1	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local
62722	1	UNKNOWN						Other Arterial/Collector/Local Road	9	22	Male	47	California	20	57	US-101	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other

62883	1	CROSSING INTERSECTION						AT/NEAR INTERSECTION	10	16	Male	64	California	6	43	E KATELLA AVE	Maintenance	Unknown	None	None/Not Applicable- Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Four-Way Intersection	Principal Arterial - Other
62889	1	AT/NEAR RECENT CRASH						INTERSTATE	6	21	Male	57	California	0	13	I-405	Construction	Unknown	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable- Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
63173	1	AT/NEAR RECENT CRASH						INTERSTATE	12	7	Female	56	California	1	50	I-10	Construction	Unknown	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable- Driver	1	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
63217	1	AT/NEAR RECENT CRASH						INTERSTATE	8	9	Female	19	California	1	55	I-10	Construction	No	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable- Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
80069	1	WORKING		ROAD WORK	MOTORIST INCURSION	Filling Pot Holes: Nolan Olson, an accomplished 64-year-old equipment operator, was filling potholes on U.S. 160 in Pagosa Springs on Feb. 2 when he was hit and severely injured.	<a href="https://www.denverpost.com/2018/02/13/cdot-employee-nolan-olson-dies/">https://www.d enverpost.com/ 2018/02/13/cd ot-employee- nolan-olson- dies/</a>	Other Arterial/Collect or/Local Road	2	2	Male	64	Colorado	11	30	US-160	Maintenance	Yes	Motor Vehicle (In Transport 1983-2004) Struck By Falling Cargo or Something That Came Loose From or Something That Was Set in Motion By a Vehicle (Since 1983)	Construction/M aintenance/Utili ty Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
80242	1	CROSSING INTERSECTION						AT/NEAR INTERSECTION	6	13	Female	55	Colorado	10	7	15TH ST	Construction	No	None	None/Not Applicable- Driver	0	NA	On Roadway	Intersection-in crosswalk	Four-Way Intersection	Minor Arterial
120023	1	CROSSING INTERSECTION						AT/NEAR INTERSECTION	1	2	Male	30	Florida	18	3	CR-431	Work Zone, Type Unknown	No	Motor Vehicle (In Transport 1983-2004) Struck By Falling Cargo or Something That Came Loose From or Something That Was Set in Motion By a Vehicle (Since 1983)	None/Not Applicable- Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	T-Intersection	Minor Arterial
120547	1	LEGALLY INTOXICATED						AT/NEAR INTERSECTION	3	2	Male	47	Florida	20	36	US-98	Work Zone, Type Unknown	No	None	None/Not Applicable- Driver	0	Intoxicated	On Roadway	Intersection- not in crosswalk	T-Intersection	Principal Arterial - Other
121312	1	UNKNOWN						INTERSTATE	6	8	Female	74	Florida	21	21	I-75	Work Zone, Type Unknown	No	None	None/Not Applicable- Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
121602	1	WORKING		UNKNOWN	UNKNOWN			AT/NEAR INTERSECTION	7	20	Male	66	Florida	2	14	SR-809	Work Zone, Type Unknown	Yes	None	None/Not Applicable- Driver	0	NA	On Roadway	Intersection- not in crosswalk	Four-Way Intersection	Principal Arterial - Other
121708	1	WORKING		ROAD WORK	MOTORIST INCURSION	Installing Traffic Signs: Florida Highway Patrol says 51-year- old Eduardo Altamar and 36- year-old Angel Montes were on the grass shoulder of the road, installing traffic signs. That's when the driver of a pickup truck lost control and drove onto the shoulder, hitting both men before continuing to hit a parked van and a light pole.	<a href="https://www fox4now.com/news/local-news/dui-charge-filed-after-roadside-worker-hit-and-killed-in-bonita-springs">https://www.fo x4now.com/ne ws/local- news/dui- charge-filed- after-roadside- worker-hit-and- killed-in-bonita- springs</a>	Other Arterial/Collect or/Local Road	8	1	Male	51	Florida	15	47	US-41	Work Zone, Type Unknown	Yes	None	None/Not Applicable- Driver	1	NA	On Roadside	Shoulder/Roads ide	Not an Intersection	Principal Arterial - Other

122031	1	UNKNOWN						Other Arterial/Collector/Local Road	6	18	Unknown	998	Florida	13	5	SR-834	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	Not an Intersection	Principal Arterial - Other
122651	1	WORKING	1356158	UTILITY	MOTORIST INCURSION	Utility worker killed by drunk driver	<a href="https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/">https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/</a>	AT/NEAR INTERSECTION	10	24	Male	52	Florida	18	50	SR-77	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	Outside Trafficway	Non-Trafficway Area	T-Intersection	Principal Arterial - Other
122651	2	WORKING	1356158	UTILITY	MOTORIST INCURSION	Utility worker killed by drunk driver	<a href="https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/">https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/</a>	AT/NEAR INTERSECTION	10	24	Male	22	Florida	18	50	SR-77	Work Zone, Type Unknown	Unknown	None	None/Not Applicable-Driver	0	NA	Outside Trafficway	Non-Trafficway Area	T-Intersection	Principal Arterial - Other
122651	3	WORKING	1356158	UTILITY	MOTORIST INCURSION	Utility worker killed by drunk driver	<a href="https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/">https://www.actionnewsjax.com/news/local/fhp-lineman-dead-after-hit-and-run-two-injured-near-chipley/859272977/</a>	AT/NEAR INTERSECTION	10	24	Male	60	Florida	18	50	SR-77	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	Outside Trafficway	Non-Trafficway Area	T-Intersection	Principal Arterial - Other
122681	1	UNKNOWN						Other Arterial/Collector/Local Road	11	30	Male	998	Florida	0	51	SR-26	Work Zone, Type Unknown	No	Other Maintenance or Construction-Created Condition	None/Not Applicable-Driver	1	NA	On Roadside	Non-Trafficway Area	Not an Intersection	Principal Arterial - Other
122763	1	LEGALLY INTOXICATED						INTERSTATE	12	7	Female	33	Florida	1	50	I-95	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
122816	1	AT/NEAR RECENT CRASH						Other Arterial/Collector/Local Road	12	7	Male	43	Florida	23	3	SR-821	Work Zone, Type Unknown	No	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
130126	1	WORKING		ROAD WORK	MOTORIST INCURSION	Reopening Lane by Removing Barrels: Ragland, a construction worker, was removing barrels from the end of the closure as it was about to reopen	<a href="https://www.11alive.com/article/traffic/construction-worker-dies-after-being-hit-on-i-85-nb-at-i-985/85-516450077">https://www.11alive.com/article/traffic/construction-worker-dies-after-being-hit-on-i-85-nb-at-i-985/85-516450077</a>	INTERSTATE	2	9	Male	42	Georgia	5	3	I-85	Construction	No	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	NA	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Interstate
130210	1	JAYWALKING				Pedestrian attempting to cross highway	<a href="https://www.11alive.com/article/news/local/union-city-fairburn/pedestrian-dies-after-attempting-to-cross-5-lane-highway-in-fairburn/85-524665071">https://www.11alive.com/article/news/local/union-city-fairburn/pedestrian-dies-after-attempting-to-cross-5-lane-highway-in-fairburn/85-524665071</a>	Other Arterial/Collector/Local Road	3	1	Male	70	Georgia	23	42	US-29 SR-14	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
130237	1	UNKNOWN						INTERSTATE	3	9	Male	75	Georgia	18	47	I-16 RAMP	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
130450	1	UNKNOWN						INTERSTATE	5	4	Male	46	Georgia	21	40	I-75	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
130472	1	CROSSING INTERSECTION				Woman killed in hit-and-run after being released from hospital	<a href="https://www.macon.com/news/local/crime/article210609024.html">https://www.macon.com/news/local/crime/article210609024.html</a>	AT/NEAR INTERSECTION	5	7	Female	46	Georgia	0	38	SR-19 VINEVILLE AVE	Maintenance	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Four-Way Intersection	Principal Arterial - Other

130482	1	WORKING		ROAD WORK	MOTORIST INCURSION	Flagging: The inmate who was hit was holding the stop/slow sign alerting drivers to the work that was going on.	<a href="https://www.wsbvtv.com/news/local/gwinnett-county/prisoner-on-work-detail-hit-killed-by-car/746553853/">https://www.wsbvtv.com/news/local/gwinnett-county/prisoner-on-work-detail-hit-killed-by-car/746553853/</a>	Other Arterial/Collector/Local Road	5	9	Male	22	Georgia	9	42	US-29 SR-8	Maintenance	Yes	None	None/Not Applicable-Driver	0	NA	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Minor Arterial
130583	2	WORKING		ROAD WORK	MOTORIST INCURSION	Picking Up Trash: two people were hit, one of them fatally, as they picked up trash early Wednesday along I-85 in Banks County....picking up debris on the road for North Carolina-based Lovin Contracting Company.	<a href="https://www.ajc.com/news/crime-law/worker-hit-killed-side-banks-county/5k5cwDajQUitOzQCORIM8LI/">https://www.ajc.com/news/crime-law/worker-hit-killed-side-banks-county/5k5cwDajQUitOzQCORIM8LI/</a>	INTERSTATE	6	6	Male	48	Georgia	7	31	I-85	Maintenance	No	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	Under Limit	On Median	Other	Not an Intersection	Interstate
130706	1	UNKNOWN						Other Arterial/Collector/Local Road	7	6	Male	45	Georgia	13	32	SR-155	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadside	Shoulder/Roadside	Not an Intersection	Minor Arterial
130978	1	UNKNOWN						Other Arterial/Collector/Local Road	6	4	Male	20	Georgia	6	16	SR-279 OLD NATIONAL HWY	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Minor Arterial
131051	1	JAYWALKING				Man hit as walking along a ramp to I-85. Victim unidentified.	<a href="https://www.ajc.com/news/crime-law/pedestrian-hit-killed-ramp-south-fulton/Gso9sFVHD7yO52ty17Vud/">https://www.ajc.com/news/crime-law/pedestrian-hit-killed-ramp-south-fulton/Gso9sFVHD7yO52ty17Vud/</a>	INTERSTATE	10	2	Male	31	Georgia	21	5	I-85	Construction	Unknown	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
131135	1	WORKING		TRUCKING	MOTORIST INCURSION	Fixing Flat: [Motorist] veered into the emergency lane, where Edmond was standing behind his tractor trailer.	<a href="https://www.nbcboston.com/news/local/construction-worker-struck-by-vehicle-concord-massachusetts/131275/">https://www.nbcboston.com/news/local/construction-worker-struck-by-vehicle-concord-massachusetts/131275/</a>	INTERSTATE	10	23	Male	51	Georgia	8	23	I-75 SR-401	Construction	Yes	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	1	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
150017	1	JAYWALKING				Man hit as walking along highway, construction visible in photos.	<a href="https://www.hawaiitribune-herald.com/2018/03/02/hawaii-news/police-id-man-killed-in-north-kona-crash/">https://www.hawaiitribune-herald.com/2018/03/02/hawaii-news/police-id-man-killed-in-north-kona-crash/</a>	Other Arterial/Collector/Local Road	3	1	Male	50	Hawaii	5	49	SR-19	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
150051	1	JAYWALKING				Man walking on the shoulder of Kunia Road when driver hit him and took off.	<a href="https://www.khon2.com/news/tip-leads-police-to-vehicle-involved-in-deadly-hit-and-run-in-kunia/">https://www.khon2.com/news/tip-leads-police-to-vehicle-involved-in-deadly-hit-and-run-in-kunia/</a>	Other Arterial/Collector/Local Road	7	10	Male	49	Hawaii	0	21	SR-750 KUNIA ROAD	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	NA	On Shoulder	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other
150087	1	CROSSING INTERSECTION				Man hit as crossing road in intersection.	<a href="https://www.khon2.com/local-news/family-mourns-victim-as-residents-push-for-more-pedestrian-safety-on-pali-hwy/">https://www.khon2.com/local-news/family-mourns-victim-as-residents-push-for-more-pedestrian-safety-on-pali-hwy/</a>	AT/NEAR INTERSECTION	10	10	Male	83	Hawaii	12	23	SR-61	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Intersection-in crosswalk	T-Intersection	Principal Arterial - Other

170894	1	WORKING		ROAD WORK	MOTORIST INCURSION	In Construction Zone: A car crossed into closed lanes and hit the worker and an empty van in the construction zone... hit and killed while helping crews replace damaged concrete on I-294 just north of the I-90 interchange, near Rosemont Friday night.	<a href="https://wgntv.com/news/construction-worker-killed-on-i-294-near-ohare/">https://wgntv.com/news/construction-worker-killed-on-i-294-near-ohare/</a>	INTERSTATE	9	14	Male	59	Illinois	22	15	I-294 TRI STATE TOLLWAY	Construction	Yes	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	1	Under Limit	Off Roadway – Location Unknown	Not Reported	Not an Intersection	Interstate
180307	1	UNKNOWN						Other Arterial/Collector/Local Road	5	31	Female	50	Indiana	21	13	SR-62	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
180392	1	JAYWALKING				Walking along side of road where there were no sidewalks was hit and killed	<a href="https://fox59.com/news/indy-man-turns-himself-in-after-seeing-story-on-fox59-about-fatal-hit-and-run/">https://fox59.com/news/indy-man-turns-himself-in-after-seeing-story-on-fox59-about-fatal-hit-and-run/</a>	Other Arterial/Collector/Local Road	7	22	Male	23	Indiana	7	26	MITTHOEFER RD	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Minor Arterial
180616	1	CROSSING INTERSECTION						AT/NEAR INTERSECTION	10	8	Female	22	Indiana	21	41	MERIDIAN ST	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Four-Way Intersection	Principal Arterial - Other
180668	2	WORKING		ROAD WORK	MOTORIST INCURSION	Foreman standing between Arrow Board and Tar Kettle Truck: He recently received a promotion to foreman of the E & B Paving crew that was working on U.S. 31 Wednesday afternoon. Nance was struck by a semi that, for some reason, did not move to the left lane and hit the arrow board, which pushed that trailer and truck into Nance and a tar kettle trailer and truck.	<a href="https://www.wthr.com/article/news/local/highway-construction-worker-killed-us-31-crash-had-just-received-promotion/531-98fac66-2c22-434a-85d8-7ea06e7960bc">https://www.wthr.com/article/news/local/highway-construction-worker-killed-us-31-crash-had-just-received-promotion/531-98fac66-2c22-434a-85d8-7ea06e7960bc</a>	Other Arterial/Collector/Local Road	11	7	Male	32	Indiana	12	40	US-31	Construction	Yes	None	None/Not Applicable-Driver	2	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
180683	1	WORKING		UNKNOWN	UNKNOWN			Other Arterial/Collector/Local Road	11	8	Male	58	Indiana	9	7	CR-200N	Construction	Yes	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Major Collector
240070	1	CROSSING INTERSECTION				Crossing road to catch bus, on way to job interview	<a href="https://wtop.com/prince-georges-county/2018/03/pedestrian-struck-and-killed-on-indian-head-highway-road-closed/">https://wtop.com/prince-georges-county/2018/03/pedestrian-struck-and-killed-on-indian-head-highway-road-closed/</a>	AT/NEAR INTERSECTION	3	22	Female	24	Maryland	5	45	SR-210	Work Zone, Type Unknown	Unknown	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Intersection-in crosswalk	Four-Way Intersection	Principal Arterial - Other
240301	1	AT/NEAR VEHICLE BREAKDOWN						INTERSTATE	8	24	Male	25	Maryland	3	48	I-95	Work Zone, Type Unknown	No	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
240324	1	UNKNOWN						Other Arterial/Collector/Local Road	9	12	Male	58	Maryland	20	11	SR-695	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways

240475	1	WORKING		ROAD WORK	ERROR ON THE JOB	Vehicle into Live Traffic for Unknown Reasons: According to a preliminary investigation, the victim, 53-year-old Johnathan Wright, of Bealeton, Virginia, was working with a crew on the ramp as a subcontractor for the Maryland Department of Transportation State Highway Administration when he was struck by a passing vehicle after exiting his	<a href="https://wjla.com/news/local/construction-worker-hit-and-run-i-295-prince-georges-county">https://wjla.com/news/local/construction-worker-hit-and-run-i-295-prince-georges-county</a>	INTERSTATE	10	1	Male	53	Maryland	1	10	I-295	Work Zone, Type Unknown	Yes	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
250294	1	WORKING		UTILITY	ERROR ON THE JOB	Backed Over by Work Truck: Preliminary investigation suggests that the man who was killed was working on the side of the road when the utility truck backed up, running him over. The man, later identified as 75-year-old Wayne Moody, of Rutland, was taken to an area hospital, where he was later pronounced dead.	<a href="https://www.nbcboston.com/news/local/construction-worker-struck-by-vehicle-concord-massachusetts/131275/">https://www.nbcboston.com/news/local/construction-worker-struck-by-vehicle-concord-massachusetts/131275/</a>	Other Arterial/Collector/Local Road	11	26	Male	75	Massachusetts	12	22	ALCOTT ROAD	Construction	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local
250300	1	WORKING	1360435	ROAD WORK	ERROR ON THE JOB	17.2 - Construction laborers - At 1:45 p.m. on November 15, 2018, an employee was removing road construction and merge signs from around guard rails. The employee was behind the vehicle during a backing maneuver and was struck and backed over by the grinding truck. The employee sustained injuries to head and torso and was killed.	<a href="https://www.osh-slc.gov/pls/imis/establishment_inspection_detail?id=1360435.015">https://www.osh-slc.gov/pls/imis/establishment_inspection_detail?id=1360435.015</a>	INTERSTATE	11	15	Male	26	Massachusetts	13	46	I-90	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	Not an Intersection	Interstate
260344	1	UNKNOWN						Other Arterial/Collector/Local Road	5	13	Male	44	Michigan	0	48	DUPONT ST	Work Zone, Type Unknown	No	Unknown	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Minor Arterial

260360	1	WORKING		ROAD WORK	MOTORIST INCURSION	Zone: A construction worker was killed early Thursday morning when an alleged drunk driver plowed into a construction zone. Michigan State Police say a woman driving a GMC Terrain was going north on I-75 when she ran off the road into the construction zone. She hit a large piece of construction equipment, and a pickup truck where two workers were	<a href="https://www.fox2detroit.com/news/construction-worker-killed-by-alleged-drunk-driver-on-i-75">https://www.fox2detroit.com/news/construction-worker-killed-by-alleged-drunk-driver-on-i-75</a>	INTERSTATE	6	14	Male	57	Michigan	0	51	I-75	Work Zone, Type Unknown	Yes	Non-Occupant Struck By Falling Cargo, or Something Came Loose From or Something That Was Set In Motion By A Vehicle (Since 1983)	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	2	NA	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Interstate
260428	1	WORKING		ROAD WORK	MOTORIST INCURSION	In Construction Zone: According to a news release, a 28-year-old woman from Marlette was driving northbound on M-25 through a construction zone when she struck the road worker.	<a href="https://www.wxyz.com/news/road-worker-hit-on-m-25-in-st-clair-county-dies-from-injuries">https://www.wxyz.com/news/road-worker-hit-on-m-25-in-st-clair-county-dies-from-injuries</a>	Other Arterial/Collector/Local Road	7	31	Male	44	Michigan	12	4	SR-25 24TH AVE	Construction	Yes	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
260612	1	WORKING		ROAD WORK	MOTORIST INCURSION	In Construction Zone: A Michigan construction worker was killed and another injured when they were struck by a car in a construction zone on U.S. 31 in Manistee County	<a href="https://www.freep.com/story/news/local/michigan/2018/09/26/construction-zone-crash-worker-killed/142984702/">https://www.freep.com/story/news/local/michigan/2018/09/26/construction-zone-crash-worker-killed/142984702/</a>	Other Arterial/Collector/Local Road	9	25	Male	20	Michigan	15	25	US-31 LAKE ST	Work Zone, Type Unknown	Yes	Unstabilized Situation Began and All Harmful Events Occurred Off of the Roadway (Since 2012)	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	NA	On Roadside	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other
260664	1	AT/NEAR VEHICLE BREAKDOWN				Woman exited stalled car and was killed as 2nd car collided into 1st stalled car	<a href="https://www.mcombdaily.com/news/local/crash-kills-woman-on-i-696-in-warren/article_56947ae2-be87-11e8-aa29-ab8ed3644500.html">https://www.mcombdaily.com/news/local/crash-kills-woman-on-i-696-in-warren/article_56947ae2-be87-11e8-aa29-ab8ed3644500.html</a>	INTERSTATE	9	21	Female	40	Michigan	1	15	I-696	Construction	No	Indication of a Stalled/Disabled Vehicle (Since 2008)	None/Not Applicable-Driver	0	NA	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate



270246	1	WORKING		ROAD WORK	MOTORIST INCURSION	occurred shortly after 2 p.m. on I-94 just west of County Road 81 in Rogers, where a crew was working in the closed-off right lane on a drilling project in preparation for road work starting next year, the patrol said. The impact in the center lane sent the pickup and the trailer it pulled spinning to the right into two workers standing in the marked-off and "relatively well	<a href="https://www.startribune.com/charges-possible-for-preventable-crash-that-killed-road-worker-on-i-94/495051691/">https://www.startribune.com/charges-possible-for-preventable-crash-that-killed-road-worker-on-i-94/495051691/</a>	INTERSTATE	10	2	Male	59	Minnesota	14	10	I-94	Construction	Yes	Other Maintenance or Construction- Created Condition	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	2	Under Limit	On Roadway	Non-Trafficway Area	Not an Intersection	Interstate
290399	1	LEGALLY INTOXICATED						Other Arterial/Collector/Local Road	7	6	Male	55	Missouri	21	44	GLENSTONE AVE	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not at Intersection-In Marked Crosswalk	Not an Intersection	Principal Arterial - Other
290586	1	UNKNOWN						Other Arterial/Collector/Local Road	9	9	Female	39	Missouri	2	45	TROOST AVE	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Minor Arterial
300131	1	WORKING		ROAD WORK	MOTORIST INCURSION	Zone: Construction workers with the Montana Department of Transportation were working on the off ramp when BPD says a flatbed truck hit the 52-year-old man. He was pronounced dead at the scene. At this time, the family would not like his name released. Both roads had one lane open while construction was being done on the off ramp when the incident	<a href="https://www.kulr8.com/news/fatal-road-construction-incident-on-i-94-investigation/article_1d5c0796-e2a8-53fa-9ef7-6b1dab19b4d8.html">https://www.kulr8.com/news/fatal-road-construction-incident-on-i-94-investigation/article_1d5c0796-e2a8-53fa-9ef7-6b1dab19b4d8.html</a>	INTERSTATE	10	24	Male	52	Montana	15	24	I-90	Construction	Yes	None	None/Not Applicable-Driver	3	Under Limit	On Roadside	Non-Trafficway Area	Not an Intersection	Interstate
320279	1	LEGALLY INTOXICATED						AT/NEAR INTERSECTION	7	4	Male	51	Nevada	0	9	SR-592 E FLAMINGO RD	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Intersection-in crosswalk	Four-Way Intersection	Minor Arterial
360024	1	UNKNOWN						Other Arterial/Collector/Local Road	1	12	Male	46	New York	23	14	SR-146	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other

360136	1	WORKING	1307411	UTILITY	MOTORIST INCURSION	Electricians - Hutchinson River Parkway - At 10:45 a.m. on April 4, 2018, Employee #1 and a coworker were walking along the shoulder of a road to retrieve equipment from their van. A SUV traveling on the far left lane going southbound on the road crossed two right lanes, hit the a barrier, and drove on the shoulder where Employee # 1 and his	<a href="https://www.osha.gov/pls/imis/establishment_inspection_detail?id=1307411.015">https://www.osha.gov/pls/imis/establishment_inspection_detail?id=1307411.015</a>	Other Arterial/Collector or Local Road	4	4	Male	57	New York	10	26	SR-908A HUTCHINSON RIVER PKWY	Maintenance	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadside	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other
360140	1	WORKING		ROAD WORK	MOTORIST INCURSION	Operation: Goshen, NY -- April 3, 2018, James Demmer died in a worksite accident after being struck by a car. Local media reports place the accident between 8 and 9 pm near 3317 Route 207. A spokesman for the New York State Police indicated that Mr. Demmer was cleaning up after performing a paving job when the accident occurred. A	<a href="https://www.texas-wrongful-death-lawyer.net/90066/james-demmer-accident-goshen-ny.htm">https://www.texas-wrongful-death-lawyer.net/90066/james-demmer-accident-goshen-ny.htm</a>	Other Arterial/Collector or Local Road	4	3	Male	58	New York	20	30	SR-207	Maintenance	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
360555	1	WORKING	1346271	ROAD WORK	ERROR ON THE JOB	400 East 74th Street - At 9:43 a.m. on September 13, 2018, an employee was standing in front of a concrete cutter when it ran over him. The employee was crushed beneath the vehicles front right tire, killing him.	<a href="https://www.osha.gov/pls/imis/establishment_inspection_detail?id=1346271.015">https://www.osha.gov/pls/imis/establishment_inspection_detail?id=1346271.015</a>	Other Arterial/Collector or Local Road	9	13	Male	66	New York	9	43	E 74TH ST	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local
370457	1	JAYWALKING				Unclear why woman was on interstate.	<a href="https://spectrumslocalnews.com/nc/charlotte/news/2018/05/05/pedestrian-hit--killed-on-i-77">https://spectrumslocalnews.com/nc/charlotte/news/2018/05/05/pedestrian-hit--killed-on-i-77</a>	INTERSTATE	5	5	Female	21	North Carolina	5	4	I-77	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
370665	1	UNKNOWN						Other Arterial/Collector or Local Road	6	23	Male	34	North Carolina	2	16	WARD BLVD	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local
390151	1	WORKING		ROAD WORK	MOTORIST INCURSION	ODOT worker killed on I-680 when struck by vehicle	<a href="https://www.wfmj.com/story/37745755/family-of-odot-worker-killed-on-680-urges-drivers-to-pay-attention-and-slow-down">https://www.wfmj.com/story/37745755/family-of-odot-worker-killed-on-680-urges-drivers-to-pay-attention-and-slow-down</a>	INTERSTATE	3	15	Male	53	Ohio	12	36	I-680	Maintenance	No	None	None/Not Applicable-Driver	1	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate

390671	1	WORKING		ROAD WORK	MOTORIST INCURSION	Operation: A construction worker with Gerken Paving has been killed in an accident on US 24. That's according to the Ohio State Highway Patrol. Officials have identified the victim as 42-year-old Nathan Soto from Napoleon...Officials say 34-year-old Michael Massucci from Waterville was driving in the left lane when he changed lanes and traveled too far over, hitting	<a href="https://www.13abc.com/content/news/Construction-worker-killed-in-US-24-accident-492027011.html">https://www.13abc.com/content/news/Construction-worker-killed-in-US-24-accident-492027011.html</a>	Other Arterial/Collector/Local Road	8	29	Male	42	Ohio	16	1	US-24	Work Zone, Type Unknown	Yes	Other Maintenance or Construction-Created Condition	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	1	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other Freeways and Expressways
390714	1	WORKING		ROAD WORK	ERROR ON THE JOB	Backed over by Work Truck: Streetsboro police Lt. Patricia Wain said 59-year-old construction worker Robert Partington of Boardman was working inside the construction zone when a 2014 Peterbilt truck, being driven by a 31-year-old Akron man, backed up and struck him. Partington was pronounced dead at the scene, police said.	<a href="https://www.record-courier.com/news/20180914/streetsboro-pd-worker-struck-killed-by-construction-vehicle-on-i-480">https://www.record-courier.com/news/20180914/streetsboro-pd-worker-struck-killed-by-construction-vehicle-on-i-480</a>	INTERSTATE	9	12	Male	59	Ohio	0	27	I-480	Construction	Yes	None	None/Not Applicable-Driver	0	NA	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Interstate
390913	1	WORKING		ROAD WORK	MOTORIST INCURSION	Repairing Guardrails: Teresa Howell, 24, of Greenwich, Ohio, was working with Lake Erie Construction of Norwalk, repairing guardrails when she was hit and killed.	<a href="https://abc6onyourside.com/news/local/person-seriously-injured-in-accident-on-us-33-near-dublin">https://abc6onyourside.com/news/local/person-seriously-injured-in-accident-on-us-33-near-dublin</a>	Other Arterial/Collector/Local Road	12	7	Female	24	Ohio	9	0	US-33	Work Zone, Type Unknown	Yes	Motor Vehicle (In Transport 1983-2004) Struck By Falling Cargo or Something That Came Loose From or Something That Was Set in Motion By a Vehicle (Since 1983)	None/Not Applicable-Driver	1	Under Limit	On Roadside	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other Freeways and Expressways
400066	1	JAYWALKING				Walking on the shoulder of busy interstate near narrowed construction area.	<a href="https://kfor.com/news/pedestrian-killed-after-being-hit-by-car-along-i-35/">https://kfor.com/news/pedestrian-killed-after-being-hit-by-car-along-i-35/</a>	INTERSTATE	2	8	Male	58	Oklahoma	6	37	I-35	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate

410281	1	WORKING		ROAD WORK	MOTORIST INCURSION	construction zone flagger Tyresa Monaghan of Kennewick died Tuesday night after a vehicle struck her on Highway 11 near Athena...The fatality occurred around 8:30 p.m. near milepost 16, where a crew was paving, according to Tom Strandberg, the regional spokesperson with the Oregon Department of Transportation. <a href="https://www.eastoregonian.com/news/local/athena-flagger-killed-on-highway-11-driver-arrested-trying-to-flee/article_d5a5a1c8-2ab0-564e-b170-79aa3564ec81.html">https://www.eastoregonian.com/news/local/athena-flagger-killed-on-highway-11-driver-arrested-trying-to-flee/article_d5a5a1c8-2ab0-564e-b170-79aa3564ec81.html</a>	Other Arterial/Collector/Local Road	8	14	Female		49	Oregon	20	30	SR-11 ODOT 8	Construction	No	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	Not an Intersection	Principal Arterial - Other
420130	1	UNKNOWN					Other Arterial/Collector/Local Road	3	30	Male		19	Pennsylvania	6	59	SR-300 283RD FIELD ARTILLY HWY	Construction	Unknown	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
420394	1	UNKNOWN					Other Arterial/Collector/Local Road	6	6	Male		42	Pennsylvania	21	32	US-422 BENJAMIN FRANKLIN HWY	Maintenance	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
420499	1	WORKING		ROAD WORK	MOTORIST INCURSION	Guard Rails...hit and run vehicle that killed a construction worker on I-90 Tuesday. Erie County Coroner Lyell Cook has identified the victim as 26-year-old Jacqueline Ohly of Stevens Point, Wisconsin. She works for a company contracted by PennDOT to string cable guide rails. Cook says she was wearing complete safety gear when she was struck	INTERSTATE	8	21	Female		26	Pennsylvania	7	28	I-90 AMVET MEM HWY	Work Zone, Type Unknown	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
450181	2	WORKING		ROAD WORK	MOTORIST INCURSION	Working in median, worked for Bagwell Fence Co.	INTERSTATE	3	28	Male		28	South Carolina	9	39	I-385	Construction	No	None	None/Not Applicable-Driver	1	Under Limit	On Median	Median/Crossing Island	Not an Intersection	Interstate
450264	1	AT/NEAR RECENT CRASH				After accident, child removed from vehicle and wandered into roadway.	INTERSTATE	4	27	Female		5	South Carolina	0	52	I-20	Work Zone, Type Unknown	No	Recent Previous Crash Scene Nearby (Since 1989)	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate

450417	1	WORKING		ROAD WORK	MOTORIST INCURSION	Truck Working on Bridge: ...tractor-trailer carrying livestock struck a piece of construction equipment in the road [boom lift truck under bridge], according to South Carolina Highway Patrol Trooper David Jones. The construction worker, identified by the Richland County Coroner's Office as Nathaniel B. Deaton, 48 [sic], of Martinsburg, IN, was thrown	<a href="https://www.wistv.com/story/38464708/update-construction-worker-struck-killed-in-i-77-collision-wednesday-identified/">https://www.wistv.com/story/38464708/update-construction-worker-struck-killed-in-i-77-collision-wednesday-identified/</a>	INTERSTATE	6	20	Male	40	South Carolina	5	0	I-77	Construction	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
450728	1	JAYWALKING				Got out of a vehicle, crossed the median and tried to cross lanes of I-20.	<a href="https://www.wistv.com/2018/10/09/year-old-identified-fatal-i-eastbound-crash/">https://www.wistv.com/2018/10/09/year-old-identified-fatal-i-eastbound-crash/</a>	INTERSTATE	10	7	Male	27	South Carolina	19	55	I-20	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
470330	1	WORKING		ROAD WORK	MOTORIST INCURSION	Standing Outside Work Vehicle: Thursday morning, a semi driver hit and killed a contract worker, Christopher Aaron Harden, as he was standing outside of a work vehicle.	<a href="https://www.wrcbtv.com/story/38214065/update-tdot-contract-worker-fatally-struck-by-semi-identified-hwy-111-reopens">https://www.wrcbtv.com/story/38214065/update-tdot-contract-worker-fatally-struck-by-semi-identified-hwy-111-reopens</a>	Other Arterial/Collector/Local Road	5	17	Male	34	Tennessee	10	0	SR-111	Construction	Yes	Other Maintenance or Construction-Created Condition	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	Under Limit	On Roadway	Shoulder/Roadside	Not an Intersection	Principal Arterial - Other Freeways and Expressways
470492	1	JAYWALKING				Got out of a vehicle, crossed the median and tried to cross lanes of I-20	<a href="https://www.wistv.com/2018/10/09/year-old-identified-fatal-i-eastbound-crash/">https://www.wistv.com/2018/10/09/year-old-identified-fatal-i-eastbound-crash/</a>	INTERSTATE	7	16	Female	34	Tennessee	1	15	I-24	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	NA	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
470915	1	LEGALLY INTOXICATED						Other Arterial/Collector/Local Road	12	10	Male	37	Tennessee	6	53	SR-30 WHITE ST	Construction	Unknown	None	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
480030	1	JAYWALKING				Pedestrian trying to cross highway from the west to the east when hit	<a href="https://www.kcbd.com/story/37192327/troopers-id-pedestrian-who-died-after-being-hit-by-vehicle-on-us-hwy-87/">https://www.kcbd.com/story/37192327/troopers-id-pedestrian-who-died-after-being-hit-by-vehicle-on-us-hwy-87/</a>	Other Arterial/Collector/Local Road	1	4	Male	27	Texas	0	4	US-87	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
480393	1	WORKING		UNKNOWN	UNKNOWN			Other Arterial/Collector/Local Road	2	6	Male	53	Texas	13	6	US-67 RAMP	Construction	Yes	None	Traveling on Prohibited Trafficway (Since 1995)	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
480397	1	AT/NEAR VEHICLE BREAKDOWN						INTERSTATE	2	7	Male	41	Texas	7	15	I-30	Construction	No	Indication of a Stalled/Disabled Vehicle (Since 2008)	Traveling on Prohibited Trafficway (Since 1995)	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate

480458	1	WORKING		ROAD WORK	MOTORIST INCURSION	Zone: A man working in a construction zone died Thursday after he was hit by a car in east Harris County, near Pasadena. Around 8:50 a.m., a red Dodge pickup truck was driving east in the 4300 block of the South Sam Houston Parkway East service road, near Cullen Boulevard, according to the Harris County Sheriff's Office. Hisham Khweis was standing at the	<a href="https://www.chron.com/neighborhood/pasadena/news/article/Car-hits-kills-construction-worker-in-Pasadena-12700464.php">https://www.chron.com/neighborhood/pasadena/news/article/Car-hits-kills-construction-worker-in-Pasadena-12700464.php</a>	Other Arterial/Collector/Local Road	2	22	Male	54	Texas	8	50	SR-18 LOOP/SAM HOUSTON PARKWAY	Construction	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadside	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
480588	1	UNKNOWN						Other Arterial/Collector/Local Road	3	2	Male	65	Texas	15	54	AIRFIELD DR	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Minor Arterial
480939	1	JAYWALKING				Walking near the right shoulder, partially in the roadway.	<a href="https://spectrmlocalnews.com/tx/south-texas-el-paso/news/2018/04/24/pedestrian-killed-on-i-35-in-south-austin-identified-">https://spectrmlocalnews.com/tx/south-texas-el-paso/news/2018/04/24/pedestrian-killed-on-i-35-in-south-austin-identified-</a>	INTERSTATE	4	21	Female	32	Texas	3	42	I-35	Construction	No	Other Maintenance or Construction-Created Condition	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
480952	1	JAYWALKING						INTERSTATE	4	24	Male	66	Texas	9	44	I-35	Construction	No	None	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
481131	1	JAYWALKING				Around 2 am, a pedestrian was hit by a car on the southbound frontage road near the US 183 flyover on I-35	<a href="https://www.ny1.com/nyc/all-boroughs/news/2018/05/07/pedestrian-killed-by-car-on-i-35--closing-frontage-road">https://www.ny1.com/nyc/all-boroughs/news/2018/05/07/pedestrian-killed-by-car-on-i-35--closing-frontage-road</a>	Other Arterial/Collector/Local Road	5	7	Male	60	Texas	2	10	I-35	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Major Collector
481477	1	JAYWALKING						INTERSTATE	6	9	Male	33	Texas	4	45	I-45	Construction	No	None	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
481891	1	CROSSING INTERSECTION						AT/NEAR INTERSECTION	7	26	Male	68	Texas	22	35	US-83 MAIN ST	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Four-Way Intersection	Principal Arterial - Other
481963	1	WORKING	1333837	ROAD WORK	ERROR ON THE JOB	2300 Lawrence St. - Masonry Contractor - At 6:45 a.m. on July 27, 2018, Employee #1 was performing flagging duties for the forklift operator. The employee approached the forklift on the operator's blind side. He was struck by and run over by forklift, and killed.	<a href="https://www.osha.gov/pls/imis/inspection_detail?id=1333837.015">https://www.osha.gov/pls/imis/inspection_detail?id=1333837.015</a>	Other Arterial/Collector/Local Road	7	27	Male	62	Texas	6	59	LAWRENCE ST	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local

482008	1	LEGALLY INTOXICATED						INTERSTATE	8	12	Male	25	Texas	5	30	I-35 STEMMONS FWY	Construction	No	None	Traveling on Prohibited Trafficway (Since 1995)	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
482286	1	WORKING		ROAD WORK	MOTORIST INCURSION	Zone: According to police, the driver of a pickup plowed through construction barrels near Overton Road and hit a utility door on a parked construction truck. The impact sent the pickup careening into the overhead sign support that was being held off the ground by the crane. The crash caused the overhead sign support to fall, hitting and killing the 35-	<a href="https://dfw.cbslocal.com/2018/09/13/road-worker-killed-driver-crashes-crane-overhead-sign/">https://dfw.cbslocal.com/2018/09/13/road-worker-killed-driver-crashes-crane-overhead-sign/</a>	INTERSTATE	9	13	Male	35	Texas	2	30	I-35E	Construction	Yes	Non-Occupant Struck By Falling Cargo, or Something Came Loose From or Something That Was Set In Motion By A Vehicle (Since 1983)	Traveling on Prohibited Trafficway (Since 1995)	1	Under Limit	Outside Trafficway	Non-Trafficway Area	Not an Intersection	Interstate
482669	1	UNKNOWN						Other Arterial/Collector/Local Road	11	1	Male	50	Texas	8	6	US-75	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other Freeways and Expressways
482732	1	JAYWALKING						INTERSTATE	10	12	Male	29	Texas	6	32	I-35	Work Zone, Type Unknown	Unknown	None	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
482797	1	JAYWALKING						INTERSTATE	10	30	Female	38	Texas	1	19	I-35	Work Zone, Type Unknown	No	None	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate
482909	1	UNKNOWN						Other Arterial/Collector/Local Road	10	25	Male	31	Texas	20	0	SR-108	Construction	No	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Major Collector
482917	1	JAYWALKING						INTERSTATE	11	12	Male	61	Texas	18	48	I-10	Work Zone, Type Unknown	No	Other Maintenance or Construction-Created Condition	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
483003	1	JAYWALKING				Couple walking along side of road where the shoulder is blocked off because of construction, not well lit, at least one of them was walking in the lane of travel.	<a href="https://www.crosstimbersgazette.com/2018/11/28/pedestrian-fatally-struck-by-vehicle-in-justin/">https://www.crosstimbersgazette.com/2018/11/28/pedestrian-fatally-struck-by-vehicle-in-justin/</a>	Other Arterial/Collector/Local Road	11	23	Male	50	Texas	20	59	FM 156	Construction	Unknown	None	None/Not Applicable-Driver	0	NA	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	Not an Intersection	Minor Arterial
483210	1	JAYWALKING						INTERSTATE	12	17	Female	43	Texas	6	16	I-35E	Construction	Unknown	None	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Crosswalk Availability Unknown	Not an Intersection	Interstate
483335	1	JAYWALKING						INTERSTATE	11	27	Male	40	Texas	13	51	I-35	Work Zone, Type Unknown	Unknown	Non-Occupant Struck Vehicle (Since 1983)	Traveling on Prohibited Trafficway (Since 1995)	0	NA	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate

510053	1	WORKING		ROAD WORK	MOTORIST INCURSION	Shoulder Closure: A driver is facing charges after a Virginia Department of Transportation (VDOT) contractor was struck and killed while setting up a work zone on I-95 in Prince George County Saturday morning...That is when 25-year-old Dustin Michael Warden, of Carson, Virginia, was struck while he was out of his vehicle setting up a shoulder charged/ <a href="https://www.wtvr.com/2018/02/03/dustin-michael-warden-dead-vdot-contractor-killed-interstate-95-samantha-hughes-charged/">https://www.wtvr.com/2018/02/03/dustin-michael-warden-dead-vdot-contractor-killed-interstate-95-samantha-hughes-charged/</a>	INTERSTATE	2	3	Male	25	Virginia	11	15	I-95	Maintenance	Yes	Motor Vehicle (In Transport 1983-2004) Struck By Falling Cargo or Something That Came Loose From or Something That Was Set in Motion By a Vehicle (Since 1983)	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	1	Under Limit	On Shoulder	Shoulder/Roadside	Not an Intersection	Interstate
510275	1	WORKING		LANDSCAPING	MOTORIST INCURSION	Sign: The investigation revealed that the landscaping truck, with an attached trailer, was stopped in the right travel lane on Old Carolina Rd just prior to Piedmont Vista Dr. [appears to be a residential area on satellite images] Workers from the truck were preparing to mow and landscape the area property when the vehicle and one of the workers were struck from behind by  <a href="https://potomaclocal.com/2018/05/23/landscaper-struck-by-prince-william-county-school-bus-killed/">https://potomaclocal.com/2018/05/23/landscaper-struck-by-prince-william-county-school-bus-killed/</a>	Other Arterial/Collector/Local Road	5	23	Male	53	Virginia	8	9	CR-625	Work Zone, Type Unknown	No	None	Construction/Maintenance/Utility Worker (Since 1995) Highway Department, Contractor, Utility Company Personnel, etc.	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Major Collector
530114	1	CROSSING INTERSECTION					AT/NEAR INTERSECTION	4	24	Male	25	Washington	21	35	E 3RD	Construction	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Intersection-in crosswalk	Four-Way Intersection	Minor Arterial
540165	1	WORKING		ROAD WORK	MOTORIST INCURSION	Outside Work Truck: A crash Thursday afternoon on Interstate 77 has claimed the life of two employees of the West Virginia Parkways Authority. One employee remains in critical condition...The crash occurred about 3:42 p.m. Thursday when the southbound tractor-trailer collided with two WVPA vehicles that were parked along the roadway,  <a href="https://www.bdtonline.com/news/local_news/second-victim-in-interstate-77-crash-succumbs-to-injuries-in-hospital/article_273071b6-70f9-5758-82bb-21bcd4f818dc.html">https://www.bdtonline.com/news/local_news/second-victim-in-interstate-77-crash-succumbs-to-injuries-in-hospital/article_273071b6-70f9-5758-82bb-21bcd4f818dc.html</a>	INTERSTATE	8	16	Male	32	West Virginia	15	42	I-77	Work Zone, Type Unknown	Yes	None	None/Not Applicable-Driver	2	Under Limit	On Roadway	Shoulder/Roadside	Not an Intersection	Interstate



540165	2	WORKING		ROAD WORK	MOTORIST INCURSION	Outside Work Truck: A crash Thursday afternoon on Interstate 77 has claimed the life of two employees of the West Virginia Parkways Authority. One employee remains in critical condition...The crash occurred about 3:42 p.m. Thursday when the southbound tractor-trailer collided with two WVPA vehicles that were parked along the roadway, <a href="https://www.bdtonline.com/news/local_news/second-victim-in-interstate-77-crash-succumbs-to-injuries-in-hospital/article_273071b6-70f9-5758-82bb-21bcd4f818dc.html">https://www.bdtonline.com/news/local_news/second-victim-in-interstate-77-crash-succumbs-to-injuries-in-hospital/article_273071b6-70f9-5758-82bb-21bcd4f818dc.html</a>	INTERSTATE	8	16	Male	21	West Virginia	15	42	I-77	Work Zone, Type Unknown	Yes	None	None/Not Applicable-Driver	2	NA	On Roadway	Shoulder/Roadside	Not an Intersection	Interstate
550086	1	CROSSING INTERSECTION					AT/NEAR INTERSECTION	2	25	Male	53	Wisconsin	0		US-18 N 35TH 4 ST	Work Zone, Type Unknown	No	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Intersection-in crosswalk	Four-Way Intersection	Principal Arterial - Other
550269	1	WORKING		PLANNING/SURVEYING	MOTORIST INCURSION	The Sheriff's Office says Schmelzer, 66, was conducting a land survey on Mathey Rd when he was hit by a vehicle. <a href="https://www.wisn.com/content/news/Fatal-Crash-in-Door-County--487924741.html">https://www.wisn.com/content/news/Fatal-Crash-in-Door-County--487924741.html</a>	Other Arterial/Collector/Local Road	7	11	Male	66	Wisconsin	8	51	MATHEY RD	Work Zone, Type Unknown	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Local
550305	1	WORKING		PLANNING/SURVEYING	MOTORIST INCURSION	According to the Mount Pleasant Police Department, Huck was marking utility locations along the median of Hwy 31 when he was hit by a car. <a href="https://www.cbs58.com/news/mount-pleasant-public-works-employee-in-critical-condition-after-being-hit-by-car-while-on-the-job">https://www.cbs58.com/news/mount-pleasant-public-works-employee-in-critical-condition-after-being-hit-by-car-while-on-the-job</a>	Other Arterial/Collector/Local Road	9	17	Male	61	Wisconsin	12	59	SR-31 GREEN BAY RD S	Work Zone, Type Unknown	Yes	None	None/Not Applicable-Driver	0	Under Limit	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Principal Arterial - Other
560070	1	LEGALLY INTOXICATED					INTERSTATE	9	13	Male	42	Wyoming	19	55	I-25	Construction	No	Other Maintenance or Construction-Created Condition	None/Not Applicable-Driver	0	Intoxicated	On Roadway	Not At Intersection-On Roadway, Not in Marked Crosswalk	Not an Intersection	Interstate